

Mark II Enterprises

Since 1965

1956-57 CONTINENTAL MARK II



ORDER TOLL FREE
50-STATES & CANADA
800-576-2752



CATALOG
EFFECTIVE
FEBURARY 2, 2012



Mark II Enterprises

A LETTER FROM JACK

We're celebrating our 47th anniversary in 2012 and want to thank all of our loyal customers. We've now moved our business to the high desert of Apple Valley, CA. Moving 55-years of parts and cars was quite an undertaking but well worth the time and effort. We now have most of our parts on the shelf for immediate delivery.

This is how it all started.

Ever since the Mark II was introduced, I was awed by it, and dreamed that some day I might own one. In 1961, I located a Mark II that had damage to the right rear quarter panel. I felt I could find the parts to repair the damage at a reasonable cost since I was in the auto dismantling business. I found what was supposed to be a N.O.S. quarter panel for \$50.00. Upon receiving the quarter, I was surprised that it was for a 1956 Lincoln Premiere! I was devastated and didn't know what to do. I advertised through the automobile media for the parts and found a Mark II that was hit in the front end. I purchased it and removed the parts I needed. I enjoyed driving and tinkering with Mark II for several months and then decided to sell the extra parts. Over the next few years, I purchased a few more cars, and decided to print a catalog listing the parts and services available. I've accumulated an enormous inventory of new, N.O.S., rebuilt and used parts. What started out to be a hobby has turned into a business! In 1979, I established a national mail order business, Reliable Motoring Accessories, specializing in custom car covers and automotive accessories. In 1989, we won the National Catalog Award with our 60-page 8-color catalog. In January 1991, I decided to semi-retire, and scale down the accessory business, as it turned out to be too time intensive preventing me from spending the time with my Mark II's and other hobbies.

After 47-years, I have accumulated over 125 Mark IIs and '49 thru 70's Lincoln's, which are in various conditions; some for parts, restoration, etc. My black Mark II received 1st place in each of the two times shown at an L.C.O.C. National Meet, including the FoMoCo® Trophy. In 1996, I completed a Bermuda Coral '57 Lincoln Premiere convertible for my wife Linda. It won first in its class in September, '96 at the L.C.O.C. Western Meet, and first in class and also the prestigious William Coughlin award (best 1951-60 Lincoln) at the '98 Western National Meet in Santa Fe, NM. Recently, it received its 2nd Emeritus award with 100 points scored. My latest project, a 1957 Mark II is in the final stages of restoration.. My Sunburst Yellow, 1956 Lincoln Premiere convertible, won the Lincoln Motor Car Award for best

primary 1949-1960 Lincoln and a 1st in its class in 2001, both first times in competition. In 2002, the '56 received a 1st in class and the William Coughlin award for best 1949-1960 Lincoln in senior class with 100 points scored. In 2003, it received 1st runner-up to Best of Show and in April of 2004, it won 1st in class again with 100 points and the Elliston H. Bell Award for Best of Show at the Western National Meet in Albuquerque, New Mexico. I have several projects in the works including '57 Mark II, '47 Cabriolet, '59, '63 and '66 Lincoln Continental Convertibles, '79 Ferrari BB512, '42 and '51 Ford Woody Wagon, and my wife's '48 Ford Anglia with a Supercharged Chevy engine.

For those who have access to a computer, view and print our latest catalog on our website www.markii.com. Most items have pictures and detailed information. Purchasing any item is easy and all personal information is encrypted by VeriSign for your security.

I'm always available to give you my personal attention, even if it's just for questions any day 8:00 am - 5:00 pm Pacific time, and weekends by chance. (Please feel free to use our Toll-Free number from the 50-States and Canada). If you get a recorded message, we're either on the phone or out in the yard.

I've recently acquired several Mark II and 1949-79 Lincoln parts cars. Inquire for your needs. The Continental Mark II Association is on hold and hopefully will resume in the near future.

Our new in-house business manufacturing plastic lenses is getting busier by the day. We have accumulated over 500 molds for most Lincoln and Mercury's and have expanded into other vehicle makes. Watch for our new steering wheels and interior knobs, manufactured as original with the color impregnated in the plastic. "If it can be made in plastic, we can do it and you can't tell them from N.O.S."

Before I conclude this letter, I suffered a near-fatal heart attack in 2003 and a serious motorcycle accident in 2004. I wish to thank everyone for their positive comments and support. My recovery has gone quite well. With the help of my wife Linda, son Brent and daughter Renee, I will continue to provide the personal attention you deserve.

Sincerely yours,

Jack Rosen



BUSINESS POLICIES

ORDER BY PHONE, FAX OR OUR WEBSITE

Call Toll Free 50-States & Canada: 800 57MARK2 (800-576-2752) or 951-686-2752
Fax 760-770-3324, 24 hours - Email: sales@markii.com - Website: www.markii.com

Our hours are Monday through Friday between the hours of 8:00 a.m. and 5:00 p.m. PST. and by chance on Saturdays. Look over the catalog and list your selections using our part numbers, descriptions, and prices. For your convenience we accept MasterCard & Visa. Visit our website www.markii.com for secure ordering.

UPS Notification via e-mail if requested — track your package the day it shipped.
Customer service and inquiries, please contact us at 800-576-2752 or 951-686-2752 or via email at info@markii.com

ORDER BY MAIL

Make checks and money orders payable to: Mark II Enterprises and call for mailing address. If ordering with a check or money order, please call for shipping charges. We try to ship within 24 hours and sometimes the same day. Any out of stock items will be put on a back-order status. Any amount of pre-paid items not available will be refunded, and you will be notified of the amount, which would be due for any substantial price increases. Please note prices and availability are subject to change without notice.

CANCELATIONS

A 3% charge for cancellation after credit card is debited. This is a bank merchant fee that we cannot recover. Orders cancelled after shipment is subject to a 20% cancellation fee and all shipping charges.

SHIPPING/HANDLING/INSURANCE CHARGES

All prices listed do not include shipping. Most items are shipped via UPS ground F.O.B. RIVERSIDE, CA and are fully insured. Minimum \$9.50 charge. UPS 3-Day Select, Second Day Air, and Next Day Air is available upon request at a slightly higher cost. Please advise a street address, as UPS will not deliver to a P.O. Box. Small items can be shipped via the Post Office from \$7.50. INTERNATIONAL: Customer's are responsible for all Custom, Duty and Brokerage Fees for any returned items including cores. No Exceptions.

RETURNS – GUARANTEES

ALL PARTS ARE 100% GUARANTEED, UNLESS SPECIFICALLY SOLD “AS IS”. Most merchandise is guaranteed for a minimum of 60 days/maximum 90, for a full refund or exchange at our discretion. Contact us if in question. Items with an written extended warranty are to the original purchaser/owner (nontransferable). Warranty starts at time of receipt of merchandise, NOT INSTALLATION DATE! Merchandise returned must be PREPAID and must be in its original condition, container and instructions. A 20% restocking fee will be charged for items returned beyond 30 days, unless there is a manufacturing defect or shipping error. Sorry, no returns on used, special orders, electrical, and fuel related items. A copy of the original invoice with a letter of explanation MUST accompany all returns - otherwise a 10% invoice research fee will be deducted. All guarantees are limited to an exchange or refund of the purchase price.

BUSINESS POLICIES (CONT.)

CORE DEPOSITS – EXCHANGES

When a rebuilt item is sold on an exchange basis, the selling price includes a rebuildable core. This is a courtesy, which eliminates the down time of your car. Without your rebuildable part, we won't have parts to sell. We prefer you send us your part first, but if you cannot, we must charge a core deposit to guarantee its return. Core deposit amounts depend on the scarcity and popularity of the item. There will be an adjustment to the core refund if your part is not rebuildable or needs major repair. Core refunds will be issued by same method of payment, normally within a few days of receipt. Exception: Some cores must be sent to manufacture for approval. This can take up to 30-days. Inquire at time of purchase.

Classic car parts are getting hard to locate. Many cores have not been returned in a timely manner or not returned at all. Without cores we can't stay in business. PLEASE RETURN CORES WITHIN 30 DAYS (unless prior arrangements are made) and enclose a copy of invoice so proper credit can be issued! Cores must be original ITEM AS SOLD, COMPLETE, ASSEMBLED & RE-BUILDABLE. CREDIT WILL BE ISSUED UPON INSPECTION. IF A CORE DEPOSIT IS REQUIRED, AND YOU CANNOT RETURN THE CORE WITHIN 30-DAYS, CALL US OR FORWARD YOUR CORE IN ADVANCE.

DAMAGED OR SHORTAGE OF MERCHANDISE

Inspect all merchandise immediately upon receipt. **DO NOT SIGN FOR COMMON CARRIER SHIPMENTS UNTIL MDSE. IS INSPECTED.** If an item is damaged or missing due to a damaged package, **contact the carrier so a claim may be processed. DO NOT SIMPLY RETURN THE PACKAGE TO US; THIS WILL VOID ANY INSURANCE CLAIM!** Catalog prices are subject to change as often times our suppliers increase costs without prior notice. When an increase is substantial, you will be notified prior to shipment. We reserve the right to refuse service to anyone.

WHY PURCHASE FROM MARK II

- | | |
|---|--|
| 1. 47 Years of Knowledge & Service | 7. Our Parts are Installed on Numerous Award Winning Mark II's and Lincoln's |
| 2. Extensive Inventory — Most Everything for Mark II and 50's & 60's Lincolns | 8. Toll Free Technical and Order Lines — Major Credit Cards Accepted |
| 3. Price Guarantee | 9. Our New Secure Website Designed for Easy on Line Ordering |
| 4. Same Day Shipping on Most Items | 10. Director of the Continental Mark II Association |
| 5. Innovative on New Product Development | |
| 6. Authenticity is our Specialty | |

TABLE OF CONTENTS

MARK II PARTS

Air Conditioning 4	Interior Items 16-18
Body Parts & Misc. Items 4-7	Lamps, Lenses, etc. 18
Brakes 7	Literature 18-19
Car Care Products 7-8	Rear Axle & Related Items 19
Cooling & Heating 8-9	Power Steering 19-20
Door & Related Items 9-10	Suspension 20-21
Electrical – Ignition 10-11	Trunk (Deck Lid) 21
Engine Parts 11-13	Transmission 21-22
Engine Gaskets 13	Rubber Kit 23
Exhaust 14	Pictures 25-26
Fuel & Carburetor 14-16	LCOC Membership Form 27
Hood & Related Items 16	Order Form 28

1956-57 Continental Mark II Parts

1949 & Later Lincoln Owners

Our extensive Lincoln parts catalog is also available on our website

AIR CONDITIONING

PART #	DESCRIPTION	PRICE	PART #	DESCRIPTION	PRICE
			AC322	Compressor return hose, 5/8" diameter, (not original), Exchange	165.00
AC001	Air compressor, 1956 with sight glass, rebuilt, exchange. Recommend rebuilding dryer (see part# AC005)	795.00	AC323	A/C Duct Hose, (through rocker panel), 1957 Only. Per 6-foot Length	37.50
AC001A	Air compressor, 1957 without sight glass, rebuilt, exchange. Recommend rebuilding dryer (See Part# AC005)	795.00	AC330	Copper gaskets 1/4" for A/C hoses, each	1.50
AC002	Air compressor clutch, used, exchange	Inquire	AC331	Copper gaskets 1/2" for A/C hoses, each	1.50
AC003	Air compressor clutch bearing	69.00	AC332	Copper gaskets 5/8" for A/C hoses, each	1.50
AC003A	Air compressor clutch/fast idle wiring harness repair assembly	15.00	BODY PARTS & MISC. ITEMS		
AC004	Automatic throttle control w/muffler (fast idle vacuum valve). Yours reconditioned to show condition	99.00	PART #	DESCRIPTION	PRICE
AC005	Drier, original (unit cut-open and cartridge replaced), exchange	225.00	BO000	Rubber Seal Kit. 23-Part #'s Interior / Exterior	Inquire
AC006	Brush set, compressor, (must use your bracket). Limited supply	99.00	BO001	Grille vertical (Center/inner/outer bar. Used, Rechrome & N.O.S)	Inquire
AC007	Expansion valve, replacement, must modify	95.00	BO002	Grille lower left/right molding, (hockey stick), used	Inquire
AC008	Decal, evaporator freon sight glass (in trunk)	7.50	BO003	Center Lower Grille Surround Stainless Joint Cover (At Hockey Sticks)	Inquire
AC009	A/C motor rewire kit. 2-red/orange/black vinyl, with bullet ends, per motor	35.00	BO004	Grille left/right, used/Rechrome	Inquire
AC009UL	Air Conditioning Motor, Lt, Used, Exch.	125.00	BO005	Rocker panel molding, right (94 5/16") Reconditioned & N.O.S. limited to stock on hand.	Inquire
AC009UR	Air Conditioning Motor, Rt, Used, Exch.	125.00	BO006	Rocker panel molding, left (94 5/16") Reconditioned & N.O.S. limited to stock on hand.	Inquire
AC320	Compressor hose, 5/8" diameter. (not original), Exchange	165.00	BO007	Rocker molding clip, each. Requires 6 Front & 3 rear per side. Exact Repro.	7.00
AC321	Compressor high-pressure hose 1/4" dia. (to condenser), 1/4" dia. (not orig.) exch.	165.00	BO007B	Rocker panels, Right & Left, N.O.S.	Inquire
			BO008S	Quarter panel skins & extensions N.O.S.	Inquire
			BO008L	Quarter panel molding, left, used, refurbished. Limited to stock	Inquire



ORDERS: 800-57-MARK2 (50-STATES / CANADA) : 951-686-2752 • FAX: 760-770-3324

VISIT OUR WEBSITE AT: www.markii.com • E-MAIL: sales@markii.com

PAGE 4

**BODY PARTS &
MISC. ITEMS (CONT.)**

PART #	DESCRIPTION	PRICE			
			BO016B	Mirror bracket, outside, exact repro.	275.00
BO008R	Quarter panel molding, right, used, refurbished. Limited to stock	Inquire	BO017	Mirror molding stainless clip, exterior. (covers mounting screw), Exact plated	85.00
BO010	Antenna, vacuum, rebuilt, in stock	Inquire	BO020	Body mounts, body to frame, exact copy, each. (Requires 16). 13/4 x 3/4 x 3/4 round	8.00
BO010D	Antenna chrome dome nut, new exact copy	49.00	BO020A	Floor Board Rubber Plugs	Inquire
BO010F	Antenna sleeve, black plastic under chrome dome nut (for original mast)	20.00	BO021	Wheel cover (hubcap) N.O.S. and used	Inquire
BO010G	Antenna rubber grommet (base to fender	25.00	BO022	Wheel cover vane, N.O.S.-limited supply (specify flat or rounded top)	Inquire
BO010H	Grommet for antenna cable & vacuum lines through firewall. Also used for vacuum lines going to heater control valve in left side of vehicle	7.50	BO022U	Wheel cover vane (used) limited supply (specify flat or rounded top)	Inquire
BO010J	Retainer clamp ring for #BO010H round rubber grommet	15.00	BO023	Black satin vinyl hubcap background overlays, set of 4. Self adhesive 1-piece construction, makes installation easy. Seams hidden behind fins. No need to paint covers	55.00
BO011	Firewall rubber grommet, 9 piece set, exact copy	55.00	BO028	Window glass, 6 piece set, original color, with etched logo and date code. Specify tint or clear and Date Code	459.00
BO012	Wiper blade, TRICO RB12-2 Repro., each. Closest available for the Mark II	39.50	BO029DC	Door glass, clear as original with PPG etched logo and date	99.95
BO013L	Wiper arm, left reconditioned, Exch.	Inquire	BO029DT	Door glass, tinted as original with PPG Solex etched logo and date	99.95
BO013R	Wiper arm, right reconditioned, Exch.	Inquire	BO029QC	Quarter glass, clear as original with PPG etched logo and date	69.95
BO015	Windshield washer nozzle outlet, pair. Replacement, close to original	15.00	BO029QT	Quarter glass, tinted as original with PPG Solex etched logo and date	69.95
BO015N	Windshield wiper transmission nut, pair	22.50	BO029VC	Vent glass, clear as original with PPG etched logo and date	49.00
BO015T	Wiper transmissions, with cable, used. Wiper arm attaches to splined shaft. (right/left)	Inquire	BO029VT	Vent glass, tinted as original with PPG Solex etched logo and date	49.00
BO015W	Wiper motor, Mark II, rebuilt, exchange	159.00	BO030X	Quarter window vertical felt rubbers, pair. Our own exclusive items using our own FoMoCo® style tooling. Exact as original with metal inserts and electrified flocking	175.00
BO015W12	Wiper motor, electric-conversion, New 2-speed compact design. Easy install. All 12v Lincoln's. Exchange on vacuum. Available for most 12 volt autos.	259.00	BO031	Windshield, tinted, new, in stock	Inquire
BO016	Mirror assembly, outside complete, reproduction/Used	Inquire			
BO016A	Mirror Glass Only, Beveled	Inquire			

**BODY PARTS &
MISC. ITEMS (CONT.)**

PART #	DESCRIPTION	PRICE			
			BO036C	Economy vacuum hose kit: Includes bulk hose, analysis and instructions	60.00
BO032	Windshield weather-strip Exact repro.	195.00	BO036D	Deluxe vacuum kit: 50' pre-cut numbered hoses, (includes brake hose) 7 tees, 9 firewall & 1 large antenna grommet set, 2 flat 4-hole ignition wire grommet w/retainers for frame rail, 2 aluminum tie straps & detailed instructions.	175.00
BO033	Backglass, clear or tint, used	Inquire	BO036E	Aluminum ductile tie straps. 3 pcs. Used for tying hoses, harnesses, tubes, etc. together	12.00
BO034	Back glass weather-strip. Exact repro.	210.00	BO036F	Vacuum hose tee kit, includes 7 tees	10.00
BO035	Clips, front & rear windshield molding (slips in rubber). These must be replaced if glass is removed to secure stainless trim. Requires: 12 front and 20 rear, each	2.50	BO037	Fenders, used & N.O.S.	Inquire
BO035A	Rubber seals under windshield & back glass belt molding, each. Requires 26 front & rear	2.95	BO038	Fender emblem, exact as original in chrome with gold plated star with black painted inserts as original, each.	95.00
BO035B	Clips, front and rear windshield lower belt molding, set of 13 (bolt style). Requires 26 front and rear	13.95	BO039	Fender replacement piece 3" behind headlight. Replaces rusted/damaged area	100.00
BO036	Washer bottle, used, new	Inquire	BO040	Rubber aprons behind park lamps, pair. Protect park lamps & bumpers, from thrown gravel. Includes rivets as original	30.00
BO036A	Washer bottle bracket, used	35.00	BO040R	Rubber mud guards below rear bumper as original, pair	19.00
BO036B	Windshield washer pump, rebuilt like new. Inquire on N.O.S. and used units	395.00	BO041	Rubber cushions between fender & front bumper, pair. Exact as original	14.50
BO036B1	Windshield washer pump rebuilding kit with lid	159.00	BO042F	Bumper, front, upper & lower	Inquire
BO036B2	Windshield washer pump rebuilding kit without lid	99.00	BO042R	Bumper, rear, upper & lower	Inquire
BO036BA	Care and operation of the automatic windshield washer. Detailed information of the washer pump and interior switch. Yellow sheet with green print	5.00	BO043	Bumper guards, set of 4, nice reproduction.	Inquire
BO036BC	Windshield Washer pump red cap	39.50	BO043LL	Bumper guard, left lower, chrome over brass. Nice reproduction	Inquire
BO036BE	Wiring, windshield washer pump ground/power repair harness assembly, with A/C	15.00	BO043LU	Bumper guard, left upper, chrome over brass. Nice reproduction	Inquire
			BO043RL	Bumper guard, right lower, chrome over brass. Nice reproduction	Inquire
			BO043RU	Bumper guard, right upper, chrome over brass. Nice reproduction	Inquire

PLEASE NOTE:
"The Continental Mark II" is not a "Lincoln". When referring to a Mark II, do not use the word "Lincoln" as you may receive an incorrect item.



**BODY PARTS &
MISC. ITEMS (CONT.)**

PART #	DESCRIPTION	PRICE			
			BR007	Brake shoes, premium riveted, front 2 wheels, exchange	79.00
BO049	License plate front bracket, upper & lower. Exact copy in black	65.00	BR008R	Brake shoes, premium riveted, rear 2 wheels, exchange	79.00
BO050	License plate bracket rubber bumpers, pr	14.50	BR009RL	Wheel cylinders, front, Pair. ORIGINAL (Not Modified Replacements)	100.00
BO051	License frames, chrome, pair, "Lincoln Continental Owners Club" logo	17.50	BR010L	Wheel cylinder, left rear, new	25.00
BO053	Post weather-strip, vertical (vent to windshield post), pair. Reproduction as original #4047158/59	165.00	BR010R	Wheel cylinder, right rear, new	25.00
BO055	Ventilator air inlet duct shut off valve, right/left, each. (oval metal flap with rubber surround, inside fender)	25.00	BR013	Brake shoe return spring, 1 axle, front or rear	10.00
BO056	Rod for ventilator air inlet duct shut off valve, right/left, each	12.50	BR014	Brake shoe hold-down spring kit, rear axle	10.00
BO070	Patent plate (vehicle ID plate on left door jam) reproduction as original	Inquire	BR014A	Brake shoe hold-down spring kit, front axle (2-wheels)	10.00
			BR014B	Brake shoe adjuster spring kit, 2-frm / 2-rear	10.00
			BR015	Wheel seal, front, each (Limited stock)	22.50

BRAKES

PART #	DESCRIPTION	PRICE			
BR000	Brake rebuilding kit.. Includes: 4-NEW cylinders (not machined replacements), front & rear hoses, 8-premium riveted shoes, and spring kits. Savings over \$100.00	359.00	BR016F	Wheel bearing & race, front outer	37.50
BR000A	Brake Cylinder/Hose 6-pcs. Kit. Includes: 4-NEW Cylinders & 2-Front Hoses	157.00	BR016R	Wheel bearing & race, front inner	37.50
BR000A1	Front Wheel Cylinders & Hose Kit. 2-New ORIGINAL (Not Modified) Cyl/Hose	135.00	BR017	Wheel bearing & retainer, rear axle	60.00
BR000A2	Brake cylinder& hose 7-pcs. kit. Includes: 4-New cylinders & 2-front & rear hose	179.00	BR019	Wheel oil seal, rear	10.00
BR001	Brake booster & master cylinder, treadle-vac rebuilt exchange	325.00	BR020	Road wheel, used 15 x 6	75.00
BR0033A	Hose, master cylinder to frame 25.5"L	39.00	BR021	Brake drum, front used	Inquire
BR003A	Power brake booster hose kit. Pre-cut numbered correct diameter hoses	15.00	BR022	Brake drum, rear used	Inquire
BR004	Brake hose (front) left or right	22.00	BR023	Brake lamp switch	12.50
BR006	Brake hose (rear)	22.00	BR023A	Wiring, brake stoplight switch repair harness	15.00
			BR030A	Tires, 235 x 15 Radial. 2-7/8" white sidewall (close to 1956 specs.) Great replacement tire for a driver	Inquire
			BR030B	Tires, 8.20 x 15 B.F. Goodrich, Bias-Ply 2-1/2" whitewall, (close to '57 specs)	Inquire

CARE CARE PRODUCTS

PART #	DESCRIPTION	PRICE			
CC001GK	Car cover, custom made for Mark II, our DuraShield™ Evolution®4 material in tan or grey. Breathable/ 90% waterproof. Any auto, truck, etc., 1900 to date. 67,000 patterns.	239.00	CH003	Radiator rebuilt, exchange	Inquire
CC001PD	Car cover, custom made for Mark II, our DuraSoft© gray cotton-blend fabric is treated for water repellency. Indoor & outdoor use.	209.00	CH004	Radiator cap, chrome replacement	12.50
CC001TF	Car cover, custom made for Mark II. Soft cotton-flannel lining cotton-blend. Best indoor cover. Treated for water repellency. Tan in color. 4-year warranty.	279.00	CH004A	Radiator cap, exact as original. (Cadmium plated)	39.00
CC0010NH	Car Cover, gray Noah™ material, custom made for Mark II. Great outdoor cover, breathable, 96% waterproof. Gray. 4-year warranty. Lighter than our DuraShield™.	269.00	CH004T	Anti-freeze green tag & wire, attaches to radiator, exact copy	5.00
CC0010WS	Car Cover, WeatherShield™ material, custom made for Mark II. Best outdoor cover, breathable & weatherproof. Sheds water as soon as it hits the cover. Dust proof Machine washable & dryable. Several-colors. 4-year warranty. Lighter than our Noah™.	389.00	CH005L	Hose, radiator lower, original formed smooth type	25.00
			CH005U	Hose, radiator upper, original formed smooth type	25.00
			CH007	Thermostat, 160 degree (gasket not included). Replacement	12.50
			CH007NOS	Thermostat, 180 degree (gasket not included). Replacement	12.50
			CH008A	Thermostat housing gasket	3.50
			CH009C	Decal, anti-freeze, on radiator upper tank, (see #EN090C)	
			CH010BW	Clamps, upper, worm gear style replacement as original, each, 2-1/4"	3.50
			CH010C	Clamps, by-pass, 1-5/16", each. Original tower style	5.00
			CH010D	Clamps, double wire style, lower radiator, replacement early FoMoCo® era	Inquire
			CH012	By-pass gasket	2.50
			CH012A	By-pass metal tube, New	Inquire
			CH012AU	By-pass metal tube, Used	Inquire
			CH013	Heater rubber boot clamps, N.O.S., rectangular shape, each	7.00
			CH013A	Clamps, round. 4" to 4 3/4". Use on fresh air ducts and air cleaner, each	7.00

Custom covers are also available in 11-fabrics starting at \$101.00 for any auto, truck, etc. 1900 to date. 67,000 Master Paterns. View website: www.markii.com/cart

COOLING & HEATING

PART #	DESCRIPTION	PRICE
CH001	Radiator re-cored to original size. Ready to install, exchange.	Inquire

REMEMBER...
if you don't see it in our catalog –
call us – we locate the impossible!



ORDERS: 800-57-MARK2 (50-STATES / CANADA) : 951-686-2752 • FAX: 760-770-3324

VISIT OUR WEBSITE AT: www.markii.com • E-MAIL: sales@markii.com

PAGE 8

**COOLING & HEATING
(CONT.)**

PART #	DESCRIPTION	PRICE
CH013B	Heater core rubber connector boot. Heater core to blower motor (square pyramid shaped). Exact copy, each	Inquire
CH014	Water pump, rebuilt, 1955-57, exchange (includes gasket)	145.00
CH015	Water pump gasket	5.00
CH015A	Brass 90 degree fitting on water pump	19.95
CH016	Temperature sending unit, 1956-57, 12 volt 3/8 x 18 thread. New reproduction. Most Mark II's	75.00
CH017	Temperature sending unit, 1956, 1/4 x 18 thread	9.75
CH018AL/R	Heater cores, recond., lt/right, exchange	125.00
CH019B	Vacuum temperature control valve (in left kick panel), rebuilt exchange	125.00
CH020A	Heater blower motor, rebuilt/used (specify left or right)	Inquire
CH021	Temperature & oil sender, wire harness (3) 36"; oil pr. 24"	15.00
CH027	Fan belts, 1956-57 with factory A/C. Water pump, generator, set of 2	49.00
CH0277	Fan belts, 1957 without air conditioning, (water pump, generator), set of 2	39.00
CH028	Fan belts, water pump/generator, 1956 w/o air, set of 2	45.00
CH030	Fan blade, 6-blade, new replacement	79.00
CH031	Fan blade, 5-blade	Inquire

CH040	Vacuum heater valves on engine. Modified replacement, not original	50.00
CH040AA	Vacuum heater valve on engine. Reproduction. (Very close to Original)	115.00
CH050A	Cable ass'y, "Bowden", R/L Vent/defroster	35.00
CH050B	Cable ass'y, "Bowden" Right defroster	35.00
CH050C	Cable ass'y, "Bowden" temperature	35.00
CH050D	Cable ass'y, "Bowden" A/C	35.00

DOOR & RELATED ITEMS

PART #	DESCRIPTION	PRICE
DO010	Door Handle Pads, Pair	Inquire
DO015A	Door handle set screw, pair	2.50
DO015B	Door handle threaded shaft w/chrome end	Inquire
DO016	Door handle plastic, ready for paint	35.00
DO027XB	Plateau rubbers, "dog leg", Top of door above hinge, pair. Our own exclusive item using our own FoMoCo® style tooling. Exact as original - None finer guaranteed	125.00
DO029X	Roof rubbers above glass, pair. Our exclusive using FoMoCo® style tooling. Exact as original. Not open-cell foam copies	55.00
DO030	Door and quarter window whiskers. Cushions and seals glass. Set of 8	99.00
DO031	Door weather-strip, molded single piece, pair. Exact as original	225.00
DO034	Vent rubber seals, pair. #4047776/7	250.00
DO034A	Vent rubber vertical seals, pair, replacement. (Must cut to fit). #4047772	45.00
DO034B	Vent upper rubber caps, pair, (window stop). Rivets to top of vent frame, exact copy	72.50
DO035	Lock pull, chrome (button), exact copy	27.50
DO035A	Door lock anti-rattle chrome ring	25.00
DO037L	Door latch with star wheel, left, rebuilt in chrome. Exchange	200.00

PLEASE NOTE:
**"The Continental Mark II" is not a
 "Lincoln". When referring to a Mark II, do
 not use the word "Lincoln" as you may
 receive an incorrect item.**

DOOR & RELATED ITEMS (CONT.)

PART #	DESCRIPTION	PRICE
DO037R	Door latch w/star wheel, 1956-57 Lincoln, rebuilt, right, exchange	200.00
DO040CL	Striker plate, left, chrome, new	75.00
DO040CR	Striker plate, right, chrome, new	75.00
DO041P	Striker plate bolts with lock-nut, set of 3, un-chromed, new	7.50
DO047	Wiring, left door window and seat motor	275.00
DO048	Wiring, right door power window	185.00
DO049/50	Lock cover, chrome, lt/rt, reproduction, ea	59.00
DO052	Door lock cylinder retainer clip, set of 2	12.50
DO056U	Check strap, used	Inquire
DO060	Window channels, vertical division bar, each. Stainless 32" "U" channel mounts to vent assembly	19.50
DO061	Window channel material, vertical division bar at rear of door, per-foot	3.50
DO062	Regulator roller, window, each	3.50

ELECTRICAL-IGNITION

PART #	DESCRIPTION	PRICE
EL000KIT	Wiring Kit, SAVE 10%	3078.00
EL004A	Ignition resistor on firewall, as original	35.00
EL004AB	Wiring harness, Ignition resistor; resistor to coil; solenoid S terminal; solenoid I terminal; distributor to coil. (Specific A/C)	39.00
EL006	Voltage regulator, new	99.00
EL007C	Battery, Maintenance Free (Gel-Cel Style) 4-yr warranty. Note:See EL009A	295.00
EL008BA	Battery hold-down "J" bolts, 3/8"x10", pair	22.50
EL008BB	Battery hold-down castle nut, 3/8", pair	7.50
EL008C	Battery hold-down clamp, exact as original	75.00

EL009A Battery rubber overlays, front/sides. Copied off an original battery with the 3-dimensional Continental Star Logo. Attaches to front & sides of original size battery with rubber adhesive. A must for L.C.O.C. judging standards.
(SAVE \$20 with battery purchase) 99.00

EL010 Heater motor rewire kit. 1956 prior to March. Includes 1 each of 16" correct cloth covered wire: black, red, orange, and bullet connectors, per motor 15.00

EL0107 Heater motor rewire kit, 1957. 2-red/orange/black vinyl, w/bullet ends, for 2-motors 29.00

EL022A Battery cable, solenoid to starter. 21 3/4" (#4). #4047408. Black with lead dipped ends and ID labels as original 39.00

EL023A Cable, positive post to solenoid. 26 3/4" (#4). #4047407. Black with lead dipped ends and ID labels as original 39.00

EL024A Cable, negative post to ground. 37 1/4" (#4). #4047406. Black with lead dipped ends and ID labels as original 39.00

EL025A Ground strap, engine to firewall, 13 1/4" (#8). 4047409. Black with correct eyelets as original 12.50

EL025X Battery cable 4 piece set, as above. Save! 125.00

EL026 Window motor, main door, reconditioned, 150.00

EL026N Window motor, main door, NEW 225.00

EL026U Window motor, main door, used 150.00

EL027 Window motor rubber coupler connector 17.50

INQUIRE ON OUR NEW VENT & QUARTER MOTORS

EL028LR Vent Motor, Left Reconditioned, Exch. Inquire

EL028RR Vent Motor, Rt Reconditioned, Exchange Inquire

EL029LR Quarter motor, Lt reconditioned, Exch. Inquire

EL029RB Quarter motor, Rt reconditioned, Exch. Inquire

EL029XL Left Quarter Motor Conversion. New motor works faster & quieter than original Inquire



ORDERS: 800-57-MARK2 (50-STATES / CANADA) : 951-686-2752 • FAX: 760-770-3324

VISIT OUR WEBSITE AT: www.markii.com • E-MAIL: sales@markii.com

PAGE 10

**ELECTRICAL-IGNITION
(CONT.)**

ENGINE PARTS

PART #	DESCRIPTION	PRICE	PART #	DESCRIPTION	PRICE
EL029XR	Right Quarter Motor Conversion. New motor works faster & quieter than original	Inquire	EN000	Motor mounts, upper rectangle & lower. Set of 4. MK II & 1952-58 Lincoln	175.00
EL030U	Window/seat switch relays, used	65.00	EN002	Rubber "Donut" Below Rectangular Mount	7.50
EL031	Circuit breaker, window motor	10.00	EN0056	Engine, rebuilds long & short blocks, cylinder heads, etc.	Inquire
EL032A	Seat motor, (forward/reverse)	199.00	EN009	Freeze plugs, brass, set 6	25.00
EL032B	Seat motor, (up/down)	199.00	EN011	Cylinder head, used & rebuilt	Inquire
EL034	Seat motor gear, brass, (replaces nylon).	49.00	EN011A	Valves, exhaust, stainless	24.50
EL035	Quarter and vent motor gear	40.00	EN011B	Valves, intake, stainless	24.50
EL036	Wiring, power seat motor.	89.00	EN011C	Valve springs, intake & exhaust, each	7.50
EL037	Wiring, ashtray & cigarette lighter lights	27.50	EN011D	Valve seats, exhaust, hardened, each	10.00
EL038	Wiring, instrument panel /gauges, sockets	135.00	EN012	Rocker arm assembly, '56-57 with aluminum stands. New shafts, etc. pair	295.00
EL039	Wiring Harness, Main Engine And Headlamp Without Air Conditioning	750.00	EN0121	Rocker arm assembly, 1956-57 with steel stands. New shafts, etc. pair	295.00
EL039A	Wiring harness, main engine and headlamp with air conditioning. Exact reproduction	750.00	EN012A	Aluminum valve covers, used	Inquire
EL039B	Wiring harness, Left headlight, & generator to voltage regulator junction	79.00	EN012B	Valve cover acorn nut, each. Polished stainless, exact copy. Requires 4-per engine	7.50
EL040A	Wiring harness, cowl and body (specify with or w/o factory A/C. Exact reproduction.	1125.00	EN012C	Valve cover washer & rubber seal kit, set of 4	15.00
EL040B	Wiring, oil, temperature, air conditioning, & S.I.P. relay	Inquire	EN012D	Valve cover polished washers, set of 4	6.50
EL041A	Ignition switch, without cylinder & keys	35.00	EN013	Piston w/pin, set of 8 w/pin. Most sizes in stock	359.00
EL041B	Ignition cylinder w/ 2 Ford "Logo" keys	27.50	EN013PB	Pin bushing, each	6.50
EL041D1	Key blanks, ignition & trunk, Replacement	20.00	EN014	Piston ring set, "Cast iron" Most sizes in stock	75.00
EL042	Headlight switch (N.O.S.)	69.00	EN015	Rod bearings, each. Most sizes available	11.00
EL044	Flasher, directional	12.50	EN016	Main bearing set. Most sizes available	175.00

**Save up to 20% on
Engine Rebuilding Kits.**

ENGINE PARTS (CONT.)

PART #	DESCRIPTION	PRICE		PRICE
EN017	Cam bearings	74.00	EN038A	Vacuum advance, single diaphragm, N.O.S. (1957 only). Exchange. 250.00
EN018	Camshaft, reground to stock specifications	Inquire	ENO38ARB	Vacuum advance, single diaphragm, rebuilt, exchange (1957 only), Exchange 125.00
EN018A	Camshaft, our exclusive grind for quicker acceleration, exchange	150.00	EN038RB	Vacuum advance dual diaphragm, rebuilt, exchange (1956 only), Exchange 150.00
EN019	Lifters, hydraulic, premium heavy-duty	2.99	EN039D	Distributor, rebuilt, 1956, with tachometer, exchange. Include points & condenser. 1956 has dual diaphragm, not included 225.00
EN020	Push rods, new heavy duty. 9 9/16" length	7.50	EN039S	Distributor, rebuilt, 1957, exchange. Include points & condenser. 1957 has single diaphragm, not included 225.00
EN020U	Push rods, used. Specify length: 8 9/16"; 9 9/16"; or 9 25/32"	Inquire	EN040	Distributor cap, 1957 27.50
EN021	Oil filter, 1956 canister insert type	12.50	EN040A	Distributor cap, 1956 30.00
EN021A	Oil filter, 1957 screw-on type	8.50	EN04156K	Ignition tune-up kit, 1956. Cap, rotor, points & condenser, 8 plugs 109.00
EN021B	Oil breather cap, Mark II (black in color)	30.00	EN04157K	Ignition tune-up kit, 1957 (as above) 99.95
EN021C	Oil breather cap, Mark II (chrome)	Inquire	EN0415PT	Pertronix Electronic Ignition Conversion Kit. Eliminates Points & Condenser. Hidden in Distributor. Easy Installation. 1957 Models 105.00
EN021K	Oil filter adapter kit. Convert from messy cartridge to 1957 spin-on style	Inquire	EN0415PT1	Pertronix Electronic Ignition Conversion Kit. Eliminates points & condenser. Hidden in Distributor. Easy Installation. Mark II & '55 -56 Lincoln 125.00
EN022	Oil pan drain plug with gasket	12.50	EN041A6	Rotor, 1956 10.00
EN022A	Engine Oil Pan Drain Plug Gasket	.75	EN041A7	Rotor, 1957 7.50
EN023A	Oil sending unit, N.O.S. These are original and work on all Mark II's and Lincoln's. Limited to stock on hand	99.00	EN041C6	Condenser 1956 12.50
EN023W	Oil sender wire assembly: N.O.R.S. White wire with red stripe and ends. Longer but correct color	15.00	EN041C7	Condenser 1957 8.00
EN024	Oil pump, new heavy duty	115.00	EN041P6	Points 1956 17.50
EN024AU	Oil Pump Drive Shaft (9.25"Long)	45.00	EN041P7	Points 1957 10.00
EN025	Timing chain	65.00	EN042	Ignition coil, w/carmel color top 59.00
EN026A	Cam sprocket	95.00	EN042B	Ignition coil, black (early 1956) 48.00
EN026B	Crank sprocket	75.00		
EN037CSL	Vacuum tube, (distributor to Carter carburetor.), stainless, each	65.00		
EN037HS	Vacuum tube, pair, steel as original, (distributor to Holley carburator.)	85.00		



ORDERS: 800-57-MARK2 (50-STATES / CANADA) : 951-686-2752 • FAX: 760-770-3324

VISIT OUR WEBSITE AT: www.markii.com • E-MAIL: sales@markii.com

PAGE 12

ENGINE PARTS (CONT.)

PART #	DESCRIPTION	PRICE
EN0430	Ignition plug wire set with brown coil wire. Exact reproduction as original. Includes: 8 pre-cut plug wires, 90 degree boots with FoMoCo® logo, shoulder-less black boots & brown resistor coil wire	85.00
EN0430C	Coil wire only; brown in color as original	29.00
EN043A	Ignition wire grommet set, N.O.S. Includes: 8 grommet, 5 brackets & 2 aluminum tie straps. (inquire on individual pieces)	65.00
EN044	Spark plugs, resistor type, each.	2.75
EN047	Starter motor with bendix, rebuilt, exch.	165.00
EN047A	Starter motor w/o bendix, rebuilt, exch.	125.00
EN048	Starter Bendix drive, rebuilt, exchange	50.00
EN048A	Starter motor rubber seal, to bell housing	15.00
EN049	Starter relay (solenoid switch), black	35.00
EN049B	Starter relay solenoid switch original brown	59.00
EN050	Generator, rebuilt, 30-35 amp, exchange	150.00
EN051	Generator, rebuilt, 40-45 amp, exchange	150.00
EN052	Generator brush set	15.00
EN053	Wiring, generator field/ground rep. harness	15.00
EN060R	Harmonic balancer, damper, rebuilt, exch.	250.00
EN060U	Harmonic balancer, damper, rebuilt, exch.	150.00
EN0906	Decal set, 1956 without air conditioning	40.00
EN0906A	Decal set, 1956 with air conditioning	45.00
EN0907	Decal set, 1957 without air conditioning	40.00
EN0907A	Decal set, 1957 with air conditioning	45.00
EN090A	Decal, air cleaner, 1956 oil bath	5.00
EN090B	Decal, air cleaner service instructions, '57	5.00
EN090C	Decal, anti-freeze (on radiator upper tank)	5.00
EN090D	Decal, evaporator freon sight glass (in trunk). See #AC008	
EN090E	Decal, air conditioning compressor, red metal (on top)	5.00
EN090F	Decal, voltage regulator, '56, 30 amp	5.00
EN090G	Decal, voltage regulator, '57, 40 amp	5.00
EN090H	Decal, ignition coil	5.00
EN090J	Decal, fuse panel (inside cover)	5.00
EN090K	Decal, oil filter canister, 1956	6.00
EN090L	Decal, windshield washer bottle, 1956, yellow with green letters	5.00
EN090M	Decal, windshield washer bottle, 1957, white with blue letters	5.00
EN090N	Decal, generator, 1956 30 amp	5.00
EN090P	Decal, starter, 1956-57	5.00
EN099A	Engine paint, 500 degree "Hi-Temp" enamel, 11 oz aerosol spray. Exact Color	17.00

ENGINE GASKETS

PART #	DESCRIPTION	PRICE
ENG005A	Engine master overhaul gasket set	175.00
ENG006A	Valve seals, set of 16	10.00
ENG007	Intake manifold gasket set	22.50
ENG007A	Valley cover (tappet) gasket	15.00
ENG008A	Cylinder head gasket, pair. New self-sealing graphite material	49.00
ENG009	Rocker (valve) cover gasket, set of 2	22.50
ENG010	Oil pan gasket	22.50
ENG011	Rear main seal (new asbestos material)	24.00
ENG012	Timing cover set	22.50
ENG014R	Exhaust Gasket Set, 6-piece Set, '56-57 (Normally Not Used)	17.50

EXHAUST

PART #	DESCRIPTION	PRICE
EX001	Header inlet pipe, at manifold. Correct radius bend for use of our part # EX011 stainless covers. Left or right. "Aluminized" for superior durability. 5-year warranty	49.00
EX002	Gasket, header pipe, each. 3 required	3.50
EX003	Exhaust pipe to resonator, left or right. "Aluminized" for superior durability.	37.50
EX005	Exhaust pipe from resonator to muffler, left. (over axle). "Aluminized" for superior durability. 5-year warranty	65.00
EX006	Exhaust pipe from resonator to muffler, right, (over axle). "Aluminized"	65.00
EX007	Cross-over pipe	29.00
EX008	Muffler, smooth style as original. Now "Aluminized" for superior durability.	79.00
EX009	Resonator, very close to original, each	69.00
EX010	Tail pipe, S shaped. "Aluminized" for superior durability. 5-year warranty	29.00
EX011	Stainless steel conduit exhaust pipe covering, pair. Covers #EX001 exhaust header pipe	55.00
EX012	Clamps, band-style as original, 1 3/4" each. Requires 8	7.95
EX012A	Clamp, band-style as original, 1 3/4" for x-over pipe, steel, each. Requires 2	6.95
EX012U	Clamps, "A" U-bolt style as original, each. Mounts header to side pipe. Requires 2	3.95
EX013	Heat riser replacement, w/smaller weight	119.00
EX013A	Heat Riser, New Original, Exchange (w/Good Large Wheel Weight)	Inquire
EX014L	Exhaust manifold, left, used	150.00
EX014R	Exhaust manifold, right, used	225.00
EX014RX	Exhaust Gasket Set, 6-piece Set	17.50

EX069 Exhaust system, complete. Duplicated from N.O.S parts. Jig welded for easy bolt-on, do-it yourself installation. No welding necessary. Includes: resonators, mufflers, header stainless flex tubing, pipes and mufflers. Most pieces aluminized for durability. Should be painted black for authenticity.
NOTHING COMPARES TO THIS KIT669.00

EX069S Stainless Exhaust system is not recommended due to excessive residence and rattle.

FUEL & CARBURETOR

PART #	DESCRIPTION	PRICE
FS001A4278	Fuel pump, (AC brand w/threaded fittings) rebuilt, exchange. Call or send old one to verify type. We must have exact unit as ordered	185.00
FS001A4289	Fuel pump, (AC brand w/ tube fittings) rebuilt, exchange. Call or send old one to verify type. We must have exact unit as ordered	185.00
FS001C	Fuel pump, (CARTER brand) rebuilt, exchange. We must have exact unit as ordered	185.00
FS001HC	Fuel pump hose, cloth covered as original. Pump to tank line	15.00
FS001KA	Fuel pump rebuilding kit. AC pump only. (Most Mark II's)	115.00
FS001KCC	Fuel pump rebuilding kit. Carter brand	99.00
FS002	Fuel pump sediment glass bowl, new	15.00
FS003	Carburetor, Carter "WCFB", rebuilt and re-colored to show condition. Exchange	395.00
FS003C	Choke cover with spring, Carter, new	20.00
FS003CX	Choke cover spring, Carter	10.00
FS003D	Carter carburetor secondary diaphragm, (must use your stem)	59.00

PRODUCT PHOTOS
 Many photos are available
 on our Online Catalog at:
www.markii.com



ORDERS: 800-57-MARK2 (50-STATES / CANADA) : 951-686-2752 • FAX: 760-770-3324

VISIT OUR WEBSITE AT: www.markii.com • E-MAIL: sales@markii.com

PAGE 14

FUEL & CARBURETOR (CONT.)

PART #	DESCRIPTION	PRICE
FS003E	Dash pot, metal as original, new	39.00
FS003K	Carter "WCFB" carburetor rebuilding kit	69.00
FS005	Carburetor, Holley rebuilt and colored to show condition. Exchange	395.00
FS005C	Choke cover, Holley or Carter, new	12.50
FS005CX	Choke cover spring, Holley, new	12.50
FS005D	Holley carb. secondary diaphragm, new	35.00
FS005K	Holley carburetor rebuilding kit	69.00
FS006	Carburetor base gasket, requires 2	3.95
FS006SP	Holley carburetor spacer plate, black-anodized aluminum, reproduction. replaces original fibre style	35.00
FS0077KIT	Choke Tube Repair Kit. Includes: FS007A/H/HA/HB/HC	109.00
FS0077KITC	Choke Tube Repair Kit. Includes: FS007A/H1/H1A/HAC/HB/HC	109.00
FS007A	Choke tube in intake manifold, new. Correct size as original. Burned out tube causes exhaust to enter carburetor	19.95
FS007H	Choke tube, cloth covered stainless, 1956 holley carburetor. (choke housing to manifold)	30.00
FS007H1	Cloth tube covering, white. Choke heat tube insulator. Per foot	6.00
FS007H1A	Choke tube, stainless w/brass elbow, '57 Carter carb. (Choke to manifold)	29.00
FS007HA	Choke tube, stainless w/brass elbow, '56 Holley carburetor. (left carb. to manifold)	29.00

FUEL & CARBURETOR (CONT.)

PART #	DESCRIPTION	PRICE
FS007HAC	Pre-heat tube, stainless w/brass elbow, '57 Carter carb. (Lt. side carb. to manifold)	24.00
FS007HB	Choke tube inlet elbow, 1956 Holley	15.00
FS007HC	Choke tube outlet elbow, 1956-1957 Holley or Carter	15.00
FS00856	Air cleaner assembly, '56 Oil Bath	Inquire
FS00857	Air cleaner assembly, '57 Dry Filter	Inquire
FS008A	Air Cleaner Elbow, Used	Inquire
FS008B	Air Cleaner Elbow Bracket, Used	Inquire
FS008C	Air cleaner gasket, Carter, (air cleaner to carburetor)	3.95
FS008H	Air cleaner gasket, Holley 1956 oil bath, carburetor to air cleaner	3.95
FS008J	Air cleaner housing gasket set, Holley 1956 oil bath. Includes: 3 internal seals and 1 cleaner to carburetor seal	59.95
FS009	Air filter, 1957 dry element	18.50
FS010	Hose, air cleaner/heater duct, cloth covered 4" dia. x 18" length, each	29.00
FS010C	Air cleaner hose clamps, (See Part# CH013A)	
FS011C	Star nut, air cleaner & power steering pump, chrome, each	50.00
FS0199	Fuel filler hose, molded smooth as original Ethanol Safe	85.00
FS019B	Clamp, tower type "B", 2 3/4" for filler hose	5.00
FS020A	Fuel vent metal tee kit complete with clamps, etc. Replaces original rubber style	27.50
FS023	Fuel tank, Mark II, reconditioned/Used	Inquire
FS024	Fuel gauge sending unit in fuel tank, original, recond., exchange.	195.00
FS0244	Fuel gauge sending unit in fuel tank, new replacement, exchange	150.00

TRACK YOUR SHIPMENT

**UPS notification via e-mail if requested –
Track your package the day it shipped.**

FUEL & CARBURETOR (CONT.)

PART #	DESCRIPTION	PRICE
FS024A	Float for sending unit in fuel tank, new	15.00
FS024B	Gasket for sending unit in fuel tank, cork	5.00
FS025	Fuel line, tank to pump, exact as original	125.00
FS025ACSL	Fuel pump vacuum line, pump to intake vacuum block, 1956 Holley	45.00
FS025B	Fuel line, 1956 Holley carburetor to pump, steel as original	45.00
FS025BC	Fuel line, 1957 Carter carburetor to pump	45.00
FS026	Fuel Tank Mounting Straps	Inquire

HOOD & RELATED ITEMS

PART #	DESCRIPTION	PRICE
HO002A	Hood ornament, chrome. New hardened material, Show quality	149.00
HO004	Blanket pad under hood, 1956 - early '57 In production.	Inquire
HO004A	Insulation, 1957, pre-cut, 1-piece	55.00
HO004B	Insulation for 1956 in lieu of blanket, 7 pieces, pre-cut. Glue under hood	95.00
HO005	Under hood/trunk sound deadener. Original black waffle pattern. 3/32" x 3' x 4'. Cut to fit. Also used on trunk lid.	75.00
HO005L	Insulation bows, each (long)	Inquire
HO005S	Insulation bows, each (short)	Inquire
HO006	Letters, hood chrome set of 11. Non finer	125.00
HO006A	Letters, (Specify) each, New/Used	Inquire
HO007	Rubber guides along fender edge, each, (3 per side). Exact reproduction	6.00
HO008	Cowl rubber seal, (rear of hood on body), with fasteners. Exact reproduction	150.00
HO009	Rubber adjuster bumpers, 2 lower, pair. Also used for trunk	20.00

HO010	Adjuster bolts, hood & trunk, pair. Accepts our HO009 rubber bumpers	10.00
HO015	Hood hinges, Mark II, rebuilt, pair. Reinforced and aligned with new rivets, primed and ready for paint. No expense spared. We have solved the rear alignment problem on many Mark II's, exchange. NORMALLY IN STOCK	450.00
HO020	Molding, hood lower, left & right	Inquire
HO0496	Under hood lamp, 1956, original reconditioned & used, exchange. (req. 2)	Inquire
HO0497	Under hood lamp, 1957, original reconditioned & used, exchange (req. 1) "57's are slightly different"	Inquire
HO049A	Wiring, hood light wire, '57 single lamp	15.00
HO049B	Wiring, hood light wire, '56 dual lamps, ea	15.00

INTERIOR ITEMS

PART #	DESCRIPTION	PRICE
IN001	Radio, used & reconditioned to like new, exchange	Inquire
IN001A	Radios converted to AM-FM Stereo. Current late model components without altering appearance! Ipod/CD compatible	Inquire
IN004F	Speakers, front re-coned, originals, exch.	Inquire
IN004R	Speakers, rear, re-coned, originals, exch.	Inquire
IN005A	Steering wheels re-cast & painted to original Mark II solid color, exchange. Not recondi- tioned! Colors are cast into plastic, not painted. 10-yr. wrnty. Inquire on 4-interior knobs.	Inquire
IN006	Shift indicator plastic behind steering wheel Inquire on wire and color match.	100.00
IN006W	Turn Signal Switch Wire Loom (6-wire)	49.00

REMEMBER...
if you don't see it in our catalog –
call us – we locate the impossible!



ORDERS: 800-57-MARK2 (50-STATES / CANADA) : 951-686-2752 • FAX: 760-770-3324

VISIT OUR WEBSITE AT: www.markii.com • E-MAIL: sales@markii.com

PAGE 16

INTERIOR ITEMS (CONT.)

PART #	DESCRIPTION	PRICE		DESCRIPTION	PRICE
IN007	Horn Button Center. In production.	Inquire	IN019	Package tray material replacement in vinyl with exact original "open 2+1 weave" pattern (must dye to match)	35.00
IN008	Door panel interior chrome molding, lower horizontal, exchange. Refurbished like new. Limited to stock on hand	125.00	IN020A	Seat Lap Belt Anchor Kit, Pair	10.00
IN009	Garnish molding chrome caps	Inquire	IN020B	Seat lap belt, '50s style with chrome latches. Wide range of colors will compliment any color interior, per seat. For mounting, use our seat belt anchor kit, # IN020A	29.95
IN010KX	Interior carpet kit with rear seat panel. We sew in our original IN012 heel pad	695.00	IN022	Matelasse' interior fabric. Exact reproduction of factory weave in original colors. Red, blue, green, and gray.	Inquire
IN012	Carpet rubber insert (heel pad), exact copy	65.00	IN023	Interior exposed fasteners, screws and washers in chrome and nickel as original. Detailed description of sizes and location. Over 275 items	80.00
IN013	Rug nameplate, w/ Continental script, new	115.00	IN025	Switches, window & seat, new, Use your chrome knob	85.00
IN014	Gas pedal, exact as original, exchange (use your stainless surround)	175.00	IN026	Switches, window & seat, re-conditioned	65.00
IN014U	Chrome gas pedal stainless surround rims	35.00	IN026A	Clip, window switch (V-Style), set of 6	22.50
IN015	Gearshift end chrome knob	35.00	IN027	Dome lamp switch, in door post	15.00
IN016	Gearshift end plastic, ready for paint	20.00	IN028	Dimmer switch, new replacement	35.00
IN016A	Turn signal end plastic, ready for paint	19.00	IN028A	Dimmer switch rubber cap with stainless band. Exact copy. Slips over and covers the ugly switch button on floor	Inquire
IN016ASET	Gear shift & signal arm plastic knob set	35.00	IN029	Courtesy lamp round plastic lens, nice reproduction, pair. Also fits 1952-60 Lincoln & Mercury Convertibles	25.00
IN017	Glove box cardboard upper liner. Correct in every detail. Includes pre-punched screw holes and antenna trimmer access hole and fastener kit	35.00	IN029A1	Courtesy lamp assembly w/ round lens	Inquire
IN017B	Glove box door spring (correctly balanced)	7.50	IN031	Ash tray lid rubber bumpers, set of 8	28.00
IN017C	Glove box rubber bumper, pair	14.50	IN033F	Cigarette lighter, front, used	Inquire
IN018B	Headliner, 80% wool billiard cloth, ready to install. Medium blue. Personalized copy of installation & handling tips (6-Pages)	495.00	IN033R	Cigarette lighter, rear, used	Inquire
IN018D	Headliner, 85% wool broadcloth, medium gray, deep red (DSO). Ready to install. Includes a Personalized Copy of Installation & Handling Tips (6-Pages)	495.00	IN035A2	Dash Plastic 2-piece set. Around radio & left of steering column with laser embossed & gold lettering, 18 29/64"L	150.00
IN018W	Headliner, white #1 White Basket-weave, 71% Rayon, 29% Cotton, ready to install. Personalized copy of installation & handling tips (6-Pages)	485.00	IN035B	Instrument cluster background plastic. (behind gauges with 4-large holes)	45.00

INTERIOR ITEMS (CONT.)

PART #	DESCRIPTION	PRICE		
IN036	Fuel-Amp-Oil-Temp 4 in 1 gauge	Inquire	LA022	Tail lamp assemblies, bezels, etc... Inquire
IN037	Speedometer, rebuilt '56 140 mph	295.00	LA023	Backup lamp lens, clear. Exact reproduction as original. New FoMoCo® type tooling assures the finest product available. Exact lettering as original. Superior to N.O.S. 165.00
IN037A	Speedometer, rebuilt '57 120 mph	295.00	LA025	Tail lamp/backup rubber gasket, pair Inquire
IN038	Clock, replaced with N.O.S. movement	Inquire	LA026	Wiring, tail lamp & backup, each. Exact reproduction 50.00
IN039	Tachometer, rebuilt	Inquire	LA029	License lamp glass lens, rear, N.O.S. 20.00
IN041	Speedometer cable & housing, as original with rubber coating	49.00	LA030	Dome lamps, roof and dash panel Inquire
IN043	Speedometer plastic gear on cable, N.O.S. (17-tooth). Limited to stock on hand	Inquire	LA031	Wiring, tail lamp cross-over, exact 45.00
IN044	Tachometer cable & housing. NOTE: Cut rubber covering to original length	59.00	LA033	Wiring, rear license plate & trunk lamp 10.00
IN046	Tachometer gear, driven, N.O.S.	59.00		
IN050	Mirror glass silver-plated, interior. Exch.	89.00		

LAMPS, LENSES, ETC. SUPERIOR TO N.O.S.

Our lenses are manufactured in the USA from the latest state-of-the-art tooling to ensure quality of color, fit and originality including original lettering.

PART #	DESCRIPTION	PRICE
LA001	Headlamp rim, N.O.S., Repro. & used. Limited to stock on hand	Inquire
LA001A	Headlamp rim mounting spring clip, N.O.S. Limited stock (requires 3 per rim)	17.50
LA001B	Headlamp bucket cork seal, each	4.95
LA002	Headlamp wiring, w/socket pair	109.00
LA003	Parking lamp lens. Exact reproduction with FoMoCo® lettering as original. New FoMoCo® type tooling assures the finest product available. Compare to N.O.S.	42.50
LA006	Parking lamp wiring complete harness, pair. Exact as original. Not a repair kit.	65.00
LA021	Tail lamp lens. Exact reproduction as original. New FoMoCo® type tooling assures the finest product available. Exact lettering as original. Superior to N.O.S.	165.00

LITERATURE

PART #	DESCRIPTION	PRICE
LI001	Owners manual, hard bound with printed envelope. Limited to stock on hand	Inquire
LI001A	Owners manual, soft cover with printed envelope. Not a photo copy. Exact as original in color. Limited availability	Inquire
LI001AA	Owners Manual, B/W Photocopy	25.00
LI001E	Envelope for owner's manual with printed star, exact as original	5.00
LI001G	Authorized Service Policy/Warranty Document with envelope, dealers issued to original purchaser. Space for name, serial #, with authorized dealer inspection tear-off certificates	17.50
LI002	Master chassis parts catalog. Part numbers and illustrations	35.00
LI003	Holley carburetor service manual, model 4000 Ford, Lincoln, Mercury, 4-barrel	15.00

PRODUCT PHOTOS
Many photos are available
on our Online Catalog at:
www.markii.com



ORDERS: 800-57-MARK2 (50-STATES / CANADA) : 951-686-2752 • FAX: 760-770-3324

VISIT OUR WEBSITE AT: www.markii.com • E-MAIL: sales@markii.com

PAGE 18

LITERATURE (CONT.)

PART #	DESCRIPTION	PRICE			
			LI098F	CMA back issue Fall '98	4.00
LI005	Technical Data/Shop Maintenance Manual with detailed step by step procedures with illustrations & wiring diagrams. "A must for all Mark II owners and mechanics."	49.00	LI098SP	CMA back issue Spring '98	4.00
			LI098SU	CMA back issue Summer '98	4.00
LI007	Photo of Mark II, in front of FoMoCo® Plant, 12 x 18 black and white glossy print	15.00	LI098W	CMA back issue Winter '98	4.00
			LI099F	CMA back issue Summer/Fall '99	4.00
LI008	Factory Service Bulletins for 1956-57 Lincoln & Mark II. 191+ pages bound. Has all updates to the Technical Manual. "A must for all Mark II owners and mechanics."	45.00	LI099SP	CMA back issue Spring '99	4.00
			LI099W	CMA back issue Winter '99	4.00
LI009A	Bendix Radio Service Manual, new version	20.00	LI0W00	CMA back issue Winter '00	4.00
LI010	Dealer factory invoice. Includes name of original purchaser and vehicle options, etc. A unique addition of history for your Continental. FoMoCo® omitted costs. (photo copy). Advise Mark II ID number to verify we have it before ordering. Email or Fax only.	15.00	LI100	Mark II Paint and Upholstery Book. Extremely rare	Inquire
			LI101	Mark II Data Book. Extremely Rare	Inquire
LI013	Continental Mark II Association one year membership. 4 Issues per year of "The Continental" newsletter.. On hold		REAR AXLE & RELATED ITEMS		
LI013B	"The Best of the Continental" 20 years of Mark II technical information. 75-bound pages. Late Buddy Holiday publication.	39.00	PART #	DESCRIPTION	PRICE
LI013C	The Continental Story. Hardbound book with color pictures. Limited availability	Inquire	RA003	Universal joints, heavy duty, requires 3	17.50
LI014	Air Conditioning Service Manual, 192 pages. Most FoMoCo models	35.00	RA004	Driveshaft, complete with new rubber insulator, 3 U-joints, rubber support (rebuilt with new precision balance), exchange	Inquire
LI096F	CMA back issue Fall '96. First issue.	4.00	RA016	Driveshaft rubber insulator. Our exclusive design is far superior than any available. Viton rubber should last life of vehicle guaranteed. See part #RA017 for bearing.	105.00
LI097F	CMA back issue Fall '97	4.00	RA017	Driveshaft center support bearing	45.00
LI097SP	CMA back issue Spring '97	4.00	RA018	Pinion seal	25.00
LI097SU	CMA back issue Summer '97	4.00	RA019	Wheel bearing/retainer, rear. Note: see #BR017	
LI097W	CMA back issue Winter '97	4.00	RA020	Axle oil seal, rear, each. (see #BR019)	Inquire
			RA021	Differential assembly, used	Inquire
			RA021A	Differential gasket, Mark II	9.50

REMEMBER...
if you don't see it in our catalog –
call us – we locate the impossible!

POWER STEERING

PART #	DESCRIPTION	PRICE	SU003	Coil spring insulator, pair upper/lower (1-wheel)	29.00
ST001	Steering gear box assembly, rebuilt to 1957 specifications. We've solved many "wandering" problems! Normally in stock for immediate delivery. Exchange	345.00	SU004N	Coil springs, front, pair, new. Manufactured to factory specifications. Corrects the sagging front end	235.00
ST001B	Steering gear box seal kit. Includes 2-seals, washers, etc...	25.00	SU006L	Rebound bumper cone, lower (rt/lt), pr	125.00
ST001C	Steering gear box bushing, only	65.00	SU008	Spindle, used, each	40.00
ST001D	Gear bushing and seal kit for power steering gear	115.00	SU011A	Ball joint, lower, recond., each, exchange	135.00
ST002E	Steering pump, rebuilt. Eaton brand with screw-off cap, exchange	185.00	SU011B	Lower ball joint rubber dust cover, pair	15.00
ST002V	Steering pump, rebuilt. Vickers® brand with large reservoir lid, exchange	235.00	SU012A	Ball joint, upper, recond., each, exchange	135.00
ST002VB	Power steering pump bearing, w/Vickers brand pump	39.95	SU012B	Upper ball joint rubber dust cover, pair	15.00
ST002VBS	Power steering pump seal, Vickers brand with large reservoir Lid	12.50	SU021	Sway bar rubber bushing, pair	35.00
ST003	Master seal kit, Eaton brand power steering pump,	35.00	SU022	Stabilizer (sway bar) rubber bushing and hardware kit., 26 pieces	65.00
ST003FE	Reservoir filter, Eaton brand, power steering pump,	15.00	SU023	Idler arm, New	169.00
ST004	Power steering high-pressure hose. Replacement	59.00	SU024	Center steering link (drag link), reconditioned, exchange	250.00
ST005	Steering hose. Low-pressure return hose, replacement	22.50	SU025A	Tie rod, outer, recond., each (left or right)	85.00
ST006	Hose clamp, low pressure	2.00	SU026A	Tie rod, inner, recond., each (left or right)	85.00
ST007	Fan belt, power steering 40.5" x 1/2"	25.00	SU026C	Drag/Center link & tie rod rubber grease cups that keeps out the dirt and water while it seals in the grease. Set of 4	15.00
			SU027	Tie rod sleeve, N.O.S.	17.50
			SU028	Shocks, front, pair. Standard, heavy-duty, w/eye on bottom mount. OEM soft ride	115.00
			SU028EX	Shocks, front, extra heavy-duty gas-charged, pair. Eye on bottom mount. Extra firm ride	155.00

SUSPENSION

PART #	DESCRIPTION	PRICE	SU001	A-Frame bushing, lower, set of 2 (one wheel) 1952 and up	49.00
SU002	Upper control arm shaft with 2-screw type steel bushing, each. N.O.S. (Inquire on shaft only)	235.00	SU028T	Shocks, front, pair, standard, heavy-duty with crossbar on lower mount. Standard heavy-duty hydraulic. OEM Soft ride	115.00
			SU028TX	Shocks, front, extra heavy-duty, gas-charged, pair. Crossbar on lower mount. Extra-firm ride	155.00



ORDERS: 800-57-MARK2 (50-STATES / CANADA) : 951-686-2752 • FAX: 760-770-3324

VISIT OUR WEBSITE AT: www.markii.com • E-MAIL: sales@markii.com

PAGE 20

SUSPENSION (CONT.)

PART #	DESCRIPTION	PRICE	TK033	Rubber cup, upper corner of deck lid, on body (w/screw), pair	15.00
SU029	Shocks, rear, pair. Standard heavy-duty hydraulic. OEM Soft Ride	115.00	TK033B	Trunk lid lock cover spring	12.00
SU031N	Springs, rear, new 8 leaf without air conditioning, each. #4047377	375.00	TK043	Gold plated "knight head" key-lock cover	119.00
SU031W	Springs, rear, new 8 leaf with air conditioning, each. #4049967	375.00	TK044	Lock cylinder with 2 Ford keys	39.00
SU031X	Springs, rear, new 10 leaf with air conditioning. Export model. #4049959	425.00	TK047	Ornament plastic, Red-Blue-Gold, New	75.00
SU032	Spring leaf end kit (bolt & bushing), front end, per side	50.00	TK048	Chrome trunk handle ornament, used	Inquire
SU033	Rear spring insulation, per foot (installs between leaves. 2" x 1/16" x 25'). Enough for 2 springs	1.75	TK049	Wiring, trunk/license light wiring harness repair assembly	17.50
			TK049A	Trunk Lamp Lens, new	35.00
			TK058	Spare tire cover, vinyl, new, specify color	150.00
			TK059	Bumper jack assembly, used	Inquire
			TK060	Bumper jack and tool pouch, as original. Specify color	Inquire

TRUNK (DECK LID)

PART #	DESCRIPTION	PRICE	TK005	Under hood/trunk sound deadener. Original black waffle pattern 3/32" x 3 x 4. (See part #HO005)	75.00
TK009	Rubber adjuster bumpers, 2 lower (each). Also used for hood. (See part #HO009)		TK064A	Trunk carpet kit w/6-piece carpet, 3-piece rear side boards. Late '56 & '57 with late torsion hinges. Cut Pile. Nice replacement material. Ready to install. Not for authenticity. Specify color	625.00
TK010	Adjuster bolts, trunk & hood, pair. Accepts #TK009 rubber bumpers. (See part #HO010)		TK064AX	Trunk Carpet Set, "Wilton Wool, Close To Orig. 6-piece Carpet W/3-side Boards, (W/ torsion bar hinges) '56-7 Mark II. Specify Color	Inquire
TK011	Hinges, used/recond.. Early scissor style	399.00	TK064B	Trunk Carpet Kit /5-piece Side Boards, Cut Pile, {Early with Scissor Hinges}. Specify Color	650.00
TK012	Torsion bars, late 1956 & 1957, each	Inquire	TK064BX	Trunk Carpet Set, "Wilton Wool", Close To Original. 3-piece Set, '56-7 {Early W/ Sissor Style Hinges}	Inquire
TK013	Letters, trunk lid. Set of 11. Non finer	125.00			
TK013A	Letters, chrome, new, each, reproduction	Inquire			
TK013B	Rubber seals behind "CONTINENTAL" letters & handle, set of 15. Seals holes under deck lid	49.00			
TK031	Weather-strip, trunk lid	59.00			

TRANSMISSION

PART #	DESCRIPTION	PRICE
TR001	Transmission, rebuilt, exchange.	Inquire
TR002	Transmission gasket & seal kit	65.00
TR002C	Transmission pan gasket	12.50
TR002F	Transmission filter, new.	45.00

INQUIRE = Due to limited availability or under development

TRANSMISSION (CONT.)

PART #	DESCRIPTION	PRICE
TR002K	Transmission rebuilding kit. Gaskets, seals, clutches, etc.	135.00
TR003	Seal, rear transmission	8.50
TR004	Seal, front transmission	12.00
TR004A	Seal, Front Inner Transmission Pump	8.50
TR005A	Transmission mount, upper & lower, close to original, 2-piece set	45.00
TR006	Band, front, exchange	45.00
TR007	Band, rear, exchange	45.00
TR008	Transmissing Bushing Kit	80.00
TR010	Flywheel flex plate, new, 1957. Limited to stock on hand	Inquire
TR011	Flywheel flex plate, new & rebuilt. '56.	Inquire
TR012	Converter, oil or air-cooled	Inquire
TR0130	Flywheel o-ring rubber seal	15.00
TR01356	Flywheel With Ring Gear, 1956, Reconditioned, exchange	Inquire
TR01357	Flywheel With Ring Gear, 1957, Reconditioned, exchange	Inquire
TR014	Shifter shaft seal & O-ring kit	10.00
TR020	Splash guard to protect shift linkage, #4049953. Formed metal & powder-coated black. Most were discarded	35.00



ORDERS: 800-57-MARK2 (50-STATES / CANADA) : 951-686-2752 • FAX: 760-770-3324

VISIT OUR WEBSITE AT: www.markii.com • E-MAIL: sales@markii.com

PAGE 22

NOTES

NOTES





**Brake Booster & Master Cylinder
BR001**



**Brake Rebuilding Kit
4-New Cylinders, Hoses,
8-Riveted Shoes, & Springs Kits BR000 \$349**




**NEW
Front Wheel Cylinders & Hoses
BR000A1 \$135**



**Motor Mounts
New Tooling as Original
BR000**



**Hood Hnges HO015 (Above)
Trunk Hinges TK011 (Below)**



**Door Latches R/L
Rebuilt DO037L/R**



**Battery Rubber Overlays
Copies from Orig. Battery EL009A**



**Heel Pad
IN012**



**Taillight - Park Lamps - Backup Lamps
Made with New State of the Art Tooling in House
100's of Molds - Mark II - Lincoln - Mercury N.O.S. Quality Guaranteed**

**Hood Ornament
HO002A**



Fuel Vent Tee FS020A



Exhaust System EX069



Lap Belts Many Colors



Window Wipes DO030



Fuel Filler Hose FS0199



All Rubber Weather-Stripping Large Inventory



Rebuilt Antennas BO010



Mirror Arm BO016B



Electric Wiper Conversion BO015W12



Driveshaft Insulator & Bearing Mark II BR016 / BR017 Our Improved Exclusive Item



Complete Wire Harness EL039/040



Quarter Motor Conversion



Vent Motor Conversion



ORDERS: 800-57-MARK2 (50-STATES / CANADA) : 951-686-2752 • FAX: 760-770-3324

VISIT OUR WEBSITE AT: www.markii.com • E-MAIL: sales@markii.com

Lincoln and Continental Owners Club

Referred by Mark II Enterprises

Application - New Members Only

MEMBERSHIP APPLICATION

Name _____ Spouse _____
 Address _____ Home Phone (_____) _____
 City _____ State _____ Zip _____ E-mail _____

MEMBERSHIP CLASSES

MEMBERSHIP: This is an individual membership. The member if married is encouraged to list their spouse. The spouse will be known as an associate member and he/she can participate in the social activities of the club. The associate member is not eligible to vote on any matter, hold office or participate in the administrative functions of the club, or enter a Lincoln in a National Meet Concours.

JOINT MEMBERSHIP: The primary member and their spouse are both members and receive all of the member benefits with the exception that they only receive one issue of the publications. Both members have a vote, can hold National or Region offices, can enter Lincolns in a National Meet Concours and participate fully in all club activities.

LIFETIME MEMBERSHIP: The lifetime membership is based on the life of the primary member. Joint members will expire with the death of the primary member.

PRIMARY MEMBERSHIP: Available to members 24 years old or younger. Proof of age is required. Full membership privileges.

NATIONAL MEMBERSHIP DUES

US FUNDS ONLY (No Refunds)	Periodical Rate		First Class Postage	
	1 Year	5 Year	1 Year	5 Year
US (Member - 1 vote, Spouse is an Associate Member)	<input type="checkbox"/> \$36	<input type="checkbox"/> \$150	<input type="checkbox"/> \$48	<input type="checkbox"/> \$210
Canada, and Mexico (Member - 1 vote, Spouse is an Associate Member)	<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> \$48	<input type="checkbox"/> \$210
US - Joint Membership (2 votes, one publication)	<input type="checkbox"/> \$45	<input type="checkbox"/> \$195	<input type="checkbox"/> \$57	<input type="checkbox"/> \$255
Canada, and Mexico - Joint Membership (2 votes, one publication)	<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> \$57	<input type="checkbox"/> \$255
All Other Countries (Member - 1 vote, Spouse is an Associate Member)	<input type="checkbox"/> \$54	<input type="checkbox"/> \$240		
All Other Countries - Joint (Member & Spouse - 2 votes, one publication)	<input type="checkbox"/> \$63	<input type="checkbox"/> \$285		

PRIMARY MEMBERSHIP: (Age 24 or younger)

Annual Dues: \$21 US \$33 Canada/Mexico \$39 All Other Countries

LIFETIME MEMBERSHIPS: (Membership is based on the life of the primary member)

US (Member - 1 vote, Spouse is an Associate Member)

<input type="checkbox"/> \$1,000 Periodical Rate	<input type="checkbox"/> \$1,250 First Class
<input type="checkbox"/> 4 Payments of \$250 ea	<input type="checkbox"/> 4 Payments of \$312.50 ea

US (Member & Spouse - 2 votes, one publication)

<input type="checkbox"/> \$1,250 Periodical Rate	<input type="checkbox"/> \$1,600 First Class
<input type="checkbox"/> 4 Payments of \$312.50 ea	<input type="checkbox"/> 4 Payments of \$400 ea

Remit to: (make checks payable to LCOC)

LCOC
 P.O. Box 1715, Maple Grove, MN 55311-6715
 Ph. 763.420.7829 Ph. 866.427.7583 (toll free US only)
 fax 763.420.7849 E-mail: LCOC@cornelison.org
 Ph. Outside USA: 763.420.7829 Website: www.lcoc.org

Payment Enclosed - check one:

Check VISA Mastercard

Card# _____

Expiration Date _____

Signature _____

Year	Model	VIN (Serial No.)



ORDERS: 800-57-MARK2 (50-STATES / CANADA) : 951-686-2752 • FAX: 760-770-3324

VISIT OUR WEBSITE AT: www.markii.com • E-MAIL: sales@markii.com

Mark II Enterprises

13533 Hitt Road
Apple Valley, CA 92308

CHANGE SERVICE REQUESTED

Visit our website at www.markii.com

